Approved For Release 2003/01/24 : CIA-RDP63-00313A000500040002-1 25X1A A JAN 1963 MEMORANDUM FOR: Assistant Deputy Director (Research) SUBJECT : Mission Summery 1. Mission GRC-133, scheduled into the Szechwan Basin, book off 20/2336Z and landed 21/0405Z. The mission aborted approximately 85 miles after penetration because of camera malfunction. The malfunction was attributed to a rivet on one of the film spools. The AC generator failed in the descent to home base. Up to the time the AC generator failed, 25X1D 2. Mission GRC-134, the back-up mission for GRC-133 also to the Szechwan Basin, took off 23/23492 and landed 24/07202. The pilot estimated 40 percent of the mission was affected by weather. He reported the camera failed just after leaving the Szechwan Besin, and he flow directly home from that point. Subsequent information from the film processor shows that the camera failed before the mission entered the area of primary interest. The malfunction was attributed to a solenoid failure. 3. Mission GRC-135, scheduled for South China, aborted soon after take off because of a malfumetion of System XII. 4. Mission 3206, scheduled for North Vietnam, took off 27/00072 and landed 27/06922. The mission was successful with clear or scattered weather except in the Hanoi Rasin. 25X1D the manual sasin area the pilot's equipment showed System IX and System XII activity. A special readout of the System VI tape has been requested to verify the cause of System XII lock-ous. 5. Mission GRC-136, scheduled for South China, took off 27/23472 and landed 28/07052. The mission was partially successful in that the North Vietness Border and the Lao-Kay to Kun-Ming Road complex were in scattered clouds. Midway on the withdrawal leg and after the mission aircraft entered 25X1A

TOP SECRET

Handle via Control System

2

8.1 38	6. Mission 32 nd landed 31/07152 mpal because of ca	. The mission aborted after enter	31/0010z 25X1
	7. Mission 3210, scheduled to the took off 03/00102 and landed 03/11322. The pilot reported 100 percent successful with no cloud cover and only a small portion of the route in haze. The pilot reported that all equipment operated satisfactorily.		
الله المدينة ا المدينة المدينة	*	(Signed) Jack C. Ledford	
		JACK C. LEDFORD Colonel USAF	
		Assistant Director (Special Activities)	
		i	
D1	stribution: #1 - Addee		
	#2 - AD/OSA		
	#3 - OSA/C/OD	25X1A	
	#4 - OSA/OD/IDEA #5 - OSA/RB	20/1/1/	*
	A/OD/IDEA	(3 Jan 63)	

TOP SECRET